

Quarterly Effectiveness Evaluation (QEE) Report Including Summary of Barrier Repairs

Sand Creek Barrier System Time Critical Response Action (TCRA) for the Rocket Ridge Area of Open Demolition Area #2

Project No:	4100-979-01			QEE Report No:	4	
Date of QEE Site Visit:	2 September 2009		009			
Time Period Covered by	From	27 M	27 May 2009			
QEE Report:	То:	2 Sep	2 September 2009			
Dates of O&M Trips During Period Covered by QEE Report:			24 June 2009 (O&M Trip #10)			
			29 July 2009 (O&M Trip #11)			
.,	2		2 Sep	ptember 2009 (O&M Trip #12)		

<u>Summary of O&M Observations and Activities Performed During the QEE Report Period.</u> <u>Prior to the 2 September 2009 Repairs</u>

Materials found on the screens: Leaves, branches, sticks, sand and gravel. No munitions-related materials were found at the barrier (see Photo #1 in Attachment 1).

Barrier integrity:

Upstream (3-inch grid) barrier: All barrier elements were in place and there were no gaps between the screen panels and creek bed and banks. The ends of the top two horizontal wires of the second panel from the south were observed detached from the post clamping system. The tops of the panels were bowed in the direction of the water flow.

Downstream (1-inch grid) barrier: All posts and back braces were intact. The end panels had detached from the creek banks (see Photos #2 and #3). The tops of the panels were bowed in the direction of the water flow. Sand and gravel, approximately 2-3 inches deep, had accumulated in front of the third panel from the south.

Maintenance performed during O&M Trips: Inspected the barrier and removed the materials accumulated on the screens.

Summary of Barrier Repair Activities Conducted on 2 September 2009

On 2 September 2009, HDR/e²M mobilized to Ravenna Army Ammunition Plant (RVAAP) to oversee and direct the Sand Creek Barrier System O&M Subcontractor, PIKA International (PIKA), and the Construction Subcontractor, Cuyahoga Fence (Cuyahoga).

Prior to accessing the site, HDR/e²M briefed PIKA and Cuyahoga on the specifics of the scope of work, safety and health procedures to be followed, and potential hazards. Copies of the safety and health logs are included in Attachment 2 and the Employee/Visitor Sign-in Roster is

9/24/2009 1 of 16



in Attachment 3.

PIKA accessed the Barrier System Site first, to determine if any munitions-related materials are present on the screens. After inspecting the site and determining that no munitions-related materials are present, PIKA allowed HDR/e²M and Cuyahoga to initiate the repairs. HDR/e²M asked PIKA to perform a magnetometer-assisted sweep of approximately 100-150 feet of creek upstream of the Barrier System. PIKA performed the sweep and reported that no munitions-related materials were observed.

The repairs performed at the Barrier System consisted of the following:

- One new post and back brace were installed at the south end of the downstream barrier. The new post is approximately 6.5 feet south of the next post. The screen panel that was detached from the creek bank was attached to the new post. A new panel was installed and keyed into the bank in front (upstream) and at 45 degrees to the barrier line (see Photo #4).
- One new post and back brace were installed at the north end of the downstream barrier. The new post was installed at 3 feet 11 inches from the next post. The screen panel that was detached from the bank was attached to the new post amd keyed into the bank (see Photo #5).
- The height of the central screen panels was reduced. At the upstream barrier, the height of the three central panels was reduced to 12 inches (see Photo #6). At the downstream barrier, the panel height was reduced, from south to north, to: panel 1 height not changed; panel 2 16 inches; panel 3 12 inches; panel 4 11 to 12 inches; panel 5 10 to 16 inches (height varies due to uneven creek bottom); panels 6 and 7 height not changed (see Photo #7).
- The sand and gravel accumulated in front of the downstream barrier was removed (see Photo #8).

The repairs were completed on 2 September 2009. The Daily Quality Control Report is included in Attachment 4.

Barrier System Effectiveness Evaluation

System operational effectiveness:

During the QEE Report #4 period (27 May - 2 September 2009), the barrier system continued to be effective in its capacity to trap potential munitions-related debris. Before the 2 September 2009 repairs, the downstream barrier no longer provided full redundancy because of the separation of the end panels from the creek banks.

The repairs performed on 2 September 2009 restored the full redundancy of the downstream barrier and reduced the height of the central panels of both barriers. The benefits of the reduced height include:

- Reduced amount of leaves accumulated on the screens;
- Reduced water pressure on the screens;
- Less bowing of the screens and potential for screen rupture;
- Less potential for scouring of the creek banks; and
- Reduced need for screen cleaning outside of the regular O&M schedule.

9/24/2009 2 of 16



Personnel Present During QEE Site Visit and Barrier System Repairs

O&M and Repairs

HDR/e²M: Daniel Zugris

PIKA, O&M activities: Lew Kovarik


Cuyahoga Fence, Repairs: David Seiler, Merle Bryson, and Don Zadorozny

Visitors

RVAAP: Mark Patterson Ohio EPA: Eileen Mohr

Vista: Jim McGee

9/24/2009 3 of 16





Quarterly Effectiveness Evaluation Photographic Log

9/24/2009 4 of 16





Photo 1: Sand Creek Barrier System (2 September 2009, before O&M)



Photo 2: Downstream barrier, south end panel (2 September 2009, before O&M)

9/24/2009 5 of 16





Photo 3: Downstream barrier, north end panel (2 September 2009, before O&M)



Photo 4: New post and panel at south end of downstream barrier (2 September 2009)

9/24/2009 6 of 16





Photo 5: New post at north end of downstream barrier (2 September 2009)



Photo 6: Upstream panels after height reduction (2 September 2009)

9/24/2009 7 of 16






Photo 7: Downstream panels after height reduction (2 September 2009)



Photo 8: Area in front of downstream barrier after the removal of sand and gravel accumulation (2 September 2009)

9/24/2009 8 of 16





Safety and Health Logs

9/24/2009 9 of 16



SITE-SPECIFIC SAFETY AND HEALTH ORIENTATION LOG*

The undersigned acknowledge, understand, and agree with the following:

I have been briefed as to the nature of work in this project, its potential hazards, required PPE, and the route to the nearest hospital.

The Site-specific Safety and Health Plan (SSHP) has been explained to me, and is available to be referenced on site at all times.

I agree to abide by the SSHP and all procedures outlined in the SSHP. I understand that noncompliance with the SSHP may lead to

my removal from the site.

Company	HORYEZM	粉艾	Cychon Ferel	Cayahaquetacc	CUY AHOLA FORCE			
40 Hr OSHA Cert, No/Expiration (If applicable)	April 2010	May 2010	N/A	N/A	AN			
Signature	Daniel Augr	Low	Of Suk	JAMS-	(In Tobra	1		
Name	9/2/09 Daniel Zugnis	Alog Lew Kovarill	96/6 Doord Soiles	93/09 Mache Bayson	Yzor Don ZADURIL			
Date	9/2/09	40/02	9/2/8	g/s/og	9/2-03			


9/24/2009 10 of 16



TAILGATE SAFETY MEETING

PROJECT: RVAAP TCRA	-Upgrades PRO	JECT NO.	4100-979		
DATE: 9/2/09		-	8:00		
CLIENT: USACE-Oma	ha District	_			
SPECIFIC SITE LOCATION: Sand Creek, approximately 50 feet upstream of George Road Bridge					
TYPE OF WORK:Insta	llation of approved barrier system upgrade	s			
CHEMICAL USED:					
	SAFETY TOPICS PRES	SENTED			
PPE	Modified Level D				
Physical Hazards	Slips, trips, and falls, electric shock, noise, manual lifting, improper use of equipment, working with metal that may be sharp				
Health and Safety Plan	The Health and Safety Plan is kept in the e	2M vehicle			
ricaliti and Galety Flan	Stop operations, isolate area where hazard exist		guisher close for preventative purposes.		
Emergency Procedures	Summon field project manager. Situation will be		when more index Cores must taken to		
	Injured persons will be treated at the place they prevent further injury if it is necessary to move		-		
	If injury requires more than first aid administer		will be taken to hospital. If injury is seriou		
I I a a mital	the field project manager will summon emergency personnel. Robinson Memorial Hospital				
Hospital	6847 North Chestnut Street, Ravenna OH 44266				
Hospital Address 330-237-0811 or 911					
Special Equipment					
Other					
	ATTENDEED				
Name (Drint)	ATTENDEES		Cianatura		
Name (Print)			Signature		
Daniel Zugris		Daniel	Dup;		
Lew Kovarl K					
David Seiler		this.	Sulv		
Mente Bursa					
DON ZADOROZNY Won Jaderon					
		0			
	Daniel Zug	cis	•		
Meeting Conducted by:		-	###		

9/24/2009





Visitor Log

9/24/2009 12 of 16



EMPLOYEE/VISITOR DAILY SIGN-IN ROSTER*

PROJECT NO. 4100-979

SITE NAME: Sand Creek Barrier

DATE: 9/2/09

FIELD PROJECT MANAGER: Daniel Zugris

DATE	NAME	COMPANY	TIME ONSITE	OFFSITE
9/2/09	Daniel Zogni	HDR/e2M	8:00	3:30 pm
7/2/09	Lew Kovarill	PIKA	8:00	11:00
9/2/09	David Seiler	Cuphapa Fence	8:00	3:30 pm
7-2-09		2 Curshages FE	x 8:00	3:30 pm
9-2-09	DONZADORUZA		8:00	9:10
9.2-09	Mark Patterson	,	9:40	10.05
9-2-09	E. leza Mohr	OL.O EPA	9:40	10:05
9-2-09	Jim Mr Gee	Vista	10.45	11:00
				,

^{*}This roster is required for emergency response planning. All personnel arriving to and from the site must sign this roster. This Log does not replace the S&H Orientation.

9/24/2009 13 of 16



Daily Quality Control Report

9/24/2009 14 of 16



Daily Quality Control Report Sand Creek Barrier Repairs, RVAAP, Ravenna, OH

Date: 2 September 2009

Project Information	
Technical Project Manager:	Daniel Zugris
Project:	RVAAP Sand Creek Barrier
Project Number:	4100-979-01

Environmental Conditions	
Weather Conditions (Bright Sun, Clear,	Clear
Overcast, Rain, Snow):	
Temperature:	55 to 73 F
Wind (Still, Moderate, High):	Still
Humidity (Dry, Moderate, Humid):	Moderate

Personnel (include title and affiliation)

HDR/e²M Personnel: Daniel Zugris, Project Manager

Visitors Present: Eileen Mohr (Ohio EPA), Mark Patterson (RVAAP), and Jim McGee (Vista)

PIKA Personnel: Lew Kowarik, SUXOS

Cuyahoga Fence Personnel: Don Zadorozny, Subcontractor Project Manager, Merle Bryson, Technician, and David Seiler, Technician

Work Activities

Daniel Zugris conducted a health and safety meeting at 7:50 am, prior to commencement of site work. PIKA accessed the Barrier System Site first, to determine if any munitions-related materials were present on the screens. After inspecting the site and determining that no munitions-related materials are present, PIKA allowed HDR/e²M and Cuyahoga to initiate the repairs. HDR/e²M asked PIKA to perform a magnetometer-assisted sweep of approximately 100-150 feet of creek upstream of the Barrier System. PIKA performed the sweep and reported that no munitions-related materials were observed.

The repairs performed at the Barrier System consisted of the following:

- One new post and back brace were installed at the south end of the downstream barrier.
 The new post is approximately 6.5 feet south of the next post. The screen panel that
 was detached from the creek bank was attached to the new post. A new panel was
 installed and keyed into the bank in front (upstream) and at 45 degrees to the barrier
 line.
- One new post and back brace were installed at the north end of the downstream barrier. The new post was installed at 3 feet 11 inches from the next post. The screen panel that was detached from the bank was attached to the new post.
- The height of the central screen panels was reduced. At the upstream barrier, the height of the three central panels was reduced to 12 inches. At the downstream barrier, the



Daily Quality Control Report Sand Creek Barrier Repairs, RVAAP, Ravenna, OH

panel height was reduced, from south to north, to: panel 1 – height not changed; panel 2 – 16 inches; panel 3 – 12 inches; panel 4 – 11 to 12 inches; panel 5 – 10 to 16 inches (height varies due to uneven creek bottom); panels 6 and 7 – height not changed.

The sand and gravel accumulated in front of the downstream barrier was removed.

The repairs were completed at 3:30 pm.

Preparer:

Daniel Zugris

Signature: Daniel Lugn