

APPENDIX H

Site Photographs

This page intentionally left blank.



View is looking towards the northeast. Note orange paint line on edge of manhole rim. This denotes direction of incoming pipe at the bottom of the manhole.



View is looking into the manhole. Note orange line on manhole rim aligns with incoming pipe visible in the bottom of the manhole.



View of incoming pipe in manhole. Manhole bottom is at 7 ft bgs.



View is looking to the northwest.



Sample collection. View is looking eastward. Direct push drill rig visible in the background.



Photo No. 1 – CC RVAAP-83 DU01 SB01 sample intervals 0-5 ft and 5-10 ft.



Photo No. 2 – CC RVAAP-83 DU01 SB02 sample intervals 0-5 ft and 5-10 ft.



Photo No. 3 – CC RVAAP-83 DU01 SB05 sample intervals 0-5 ft, 5-10 ft, and 10-13 ft.