

1037 BUILDING - LAUNDRY WASTEWATER SUMP

SITE DESCRIPTION

This AOC consists of a concrete sump that was used as a settling tank for RVAAP laundry facilities. This sump was in operation from the early 1940s until 1992. No original file documentation exists for this site.

This site is RC because it is not eligible for IRP funding.

STATUS

RRSE RATING:

Medium

CONTAMINANTS:

Explosives, Metals

MEDIA OF CONCERN:

Soil, Groundwater

COMPLETED IRP PHASE:

PA/SI

CURRENT IRP PHASE:

RC - 2000