

Trip Report

Prime Contract No:			Report No.	9
PIKA JOB #:	11-46-163		Date:	5/30/12
Project:	Operation and Maintenance of the Sand Creek Barrier System			
Environmental Conditions:				
Weather Conditions (Bright Sun, Clear, Overcast, Rain, Snow):		Sunny		
Temperature:		62° F		
Wind (Still, Moderate, High):		still		
Humidity (Dry, Moderate, Humid):		Dry		
Field Activities:				
Description of debris inspection & removal activities: Removed sticks, mud, and leaves from barriers. No MEC/MD encountered.				
Barrier Integrity: Barriers are upright and intact.				
Assessment of any changes since previous visit: None				
Repairs made or need to be made: Sandbars on south side of creek at both barriers need cleaned out.				
Remarks:				
Visitors: Brian Stockwell - PIKA				

Health and Safety

Conducted health and safety meetings and task order meetings every morning, prior to commencement of activities.

Were there any lost time accidents this week? No Yes .

If "yes", refer attached summary of incident or OSHA report.

Quality Control			
Inspections Performed	Non-Conformances	Corrective Action (CA)	Follow-up on CA
Major Problems and Resolution:		None	
Schedule for Next Month: Follow on inspection of barrier.			
SUXOS Safety Officer	Dave Fewell Anita Thomas	Project Manager	Brian Stockwell

PHOTO LOG



PICTURE OF SAND CREEK BARRIERS UPON ARRIVAL.



PICTURE SHOWING UXO TECHNICIANS REMOVING DEBRIS FROM BARRIER.



PICTURE SHOWING BARRIERS UPON DEPARTURE

Safety Training Attendance Log

Visitor Sign-In Log



Visitors Sign-In Log

PROJECT LOCATION: RVAAP, OHIO

PROJECT SITE: O&M Sand Creek Barrier System PROJECT NO: 11-46-163

Date	Name	Representing	Equipment and PPE Level	Time	
				IN	Out
5/30/12	Brian Stockwell	PIKA	D	1145	1245

Comments: _____

