

## **APPENDIX G**

### **Site Photographs**

*This page intentionally left blank.*



View of location of former UST RV-4 located to the east of Bldg. 1026. Stake in foreground delineates the southwest corner of the geophysical survey area. Three stakes in the middle of the photo mark the boring locations for RV-4. Staked locations in the far background show location of former UST RV-86. Direct-push drill rig in left portion of photo is advancing borings at former UST RV-87.



View of boring locations at former USTs RV-4 (three stakes in foreground, note depression in ground may indicate previously excavated area), and RV-87 (sampling in progress) behind Building 1026.





View of boring locations for RV-87 behind Bldg. 1026. The stake not flagged in the right side of the photo indicates the location of one of the former fill pipes.



View of former fill pipe at RV-87.





View of former UST location RV-86. Stakes with yellow flagging denote direct-push boring locations. Outside stakes denote geophysical survey area. Note depressed ground surface within geophysical survey area indicating possible previously excavated area.



View of location of former UST RV-41 located at LL 6. Stakes in photo mark the boring locations for RV-41. Note depressed ground surface and standing surface water in area of borings, indicating possible previously excavated area. View is looking to the northeast.





View of boring locations at former UST RV-41 at Load Line (LL) 6. Stake in far right background indicates western extent of geophysical survey.



View of location of UST RV-46 located at former Building EE-102 (Bolton Manor) in the Depot Area. Pin flags and orange marking paint in photo indicates area of geophysical survey. View is looking to the southeast. The geophysical survey did identify an anomaly within the survey area.






View of direct push boring activities at UST RV-46. View is looking east.



View of location of former UST RV-88 located to the west of former Bldg. 1103. Stakes in photo delineates the geophysical survey area.





View of soil sampling intervals 0-5 and 5-10 ft, at boring SB02 at former UST RV-88.



View of location of former UST RV-89 at the Georges Road Treatment Plant. Chlorine building is in background, view is looking east northeast. Stakes indicate direct-push boring locations.





View of location of former UST RV-89 at the Georges Road Treatment Plant. Chlorine building is to the left, view is looking south. Orange pin flags in photo indicated extent of geophysical survey area.



View of direct-push drill rig at former UST CC-RVAAP 72-06. View is looking west northwest.





View of completed borings at former UST CC-RVAAP-72-06. Borings have been backfilled with bentonite chips.



View of staked location of former UST CC-RVAAP-72-01 at Bldg. U-3 in the Depot Area. Location of UST is approximately 20 ft to the north of Bldg. U-3 (in left of photo), next to a drainage ditch.





View of staked boring locations at former UST CC-RVAAP-72-01 at Bldg. U-3. Stakes in background are boring locations for hexavalent chromium investigation at former USTs RV-15 and RV-16. View is looking south southwest. Former Bldg. U10 is in the background.



View of former UST location CC-RVAAP-72-02 within the Atlas Scrap Yard. Concrete structures in background possible former pump islands.





View of former Atlas Scrap Yard UST location CC-RVAAP-72-02 SB03 next to concrete structure.




View of borings at former Atlas Scrap Yard UST location CC-RVAAP-72-03.





View of borings at former Atlas Scrap Yard UST location CC-RVAAP-72-03.



View of direct-push drilling activities at former UST location CC-RVAAP-72-08 at Building 71-848.





View of direct push drilling activities at former UST location RV-37 at Building A1 in the Depot Area.  
View is looking south southwest. Stakes in photo denote boring locations.



View of soil samples collected at SB03 at former UST location RV-37 at Building A1.





View of concrete slab of former Bldg. A6 located within the Depot Area. View is looking northwest.



View of direct push drilling activities at RV-97, former 550-gal UST located along the east side of former Bldg. A6. View is looking east.





Measuring excavation area of former USTs RV-17, RV-18, and RV-19. View is looking to the south.



Measuring excavation area of former USTs RV-17, RV-18, and RV-19. View is looking to the north towards former Bldg. A6 concrete pad. Stake in foreground is southwest corner of excavation area.





Photo of staked boring locations for Bldg. U-3 former USTs RV-15 and RV-16. Stakes in right forefront are staked borings for the UST investigation for CC-RVAAP-72-01.



Laying out boring locations behind Bldg. U-3.





Photo of boring locations behind Bldg. U-3. Stakes for UST CC-RVAAP-72-01 are in left background.



Photo of soil interval from 9 ft bgs showing refusal material at Bldg. U-3 SB02.





Photo of staked boring locations to the northeast of Bldg. U-6. View is looking north.



Photo of staked boring locations to the northeast of Bldg. U-6. View is looking south southwest.





Photo of staked boring locations SB02, SB03, and SB04 (far left background) at Bldg. U-6.  
View is to the east.



Photo of Bldg. U-6 soil boring SB06 sample intervals.